




Dickson Ambient Temperature Sensor

Product Images



Short Description

Dickson's new line of Replaceable Sensors allow you to monitor temperature how you want, and calibrate how you want. When your instrument is due for calibration, simply order the appropriate Replaceable Sensor

with the type of calibration you need.

Description

The Dickson RTMP Ambient Temperature Sensor allows you to monitor temperature how you want, and calibrate how you want.

When your instrument is due for calibration, simply order the appropriate Replaceable Sensor with the type of calibration you need. When you receive a new sensor – detach the old one, replace it with the new one, and then . . . you're done!

NOTE: This model is intended for use with the Dickson DWE, TSB, TWE, or TWP data loggers

Additional Information

| | |
|--------------|---|
| Explanation | Temperature Accuracy +/-1.2F from 20.0 to 122.0F 1.8 (+/-0.44C from -7.0 to 50.0C) Temperature Range 20.0 to 122.0F (0.0 to 50.0C) |
| Brand | Dickson |
| Measurements | Temperature |