



Dickson RTRH-R Replaceable Temperature & Humidity Sensor

Product Images



Short Description

Dickson RTRH-R Replaceable Temperature & Humidity Sensor. Monitor temperature & humidity how you want, and calibrate how you want. When your data logger is due for calibration, simply order the appropriate Replaceable Sensor with the type of calibration you need.

Description

Interchangeable, universal, and replaceable.

Replaceable Sensors make calibration a smooth and simple process.

The Dickson RTRH-R Replaceable Temperature & Humidity Sensor enables you to monitor temperature & humidity how you want, and calibrate how you want.

When your data logger is due for calibration, simply order the appropriate Replaceable Sensor with the type of calibration you need. When you receive the new sensor, detach the old one, replace it with the new one, and then . . . you're done!

NOTE: This model is intended for use with the Dickson DWE, TSB, TWE, or TWP data loggers.

Additional Information

| | |
|--------------|--|
| Brand | Dickson |
| Explanation | Ambient Operating RH Conditions 0 to 95% RH (non-condensing) Humidity Accuracy +/-2.0% RH from 5.0 to 95.0% RH Humidity Range 0 to 95% RH (non-condensing) Temperature Accuracy +/-0.8F from 20.0 to 120.0F 1.2 (+/-0.44C from -40.0 to 85.0C) Temperature Range -40.0 to 185.0F (-40.0 to 85.0C) |
| Measurements | Humidity, Temperature |